YMUL

MURBAY FIELD AVEAX CODE 6010

ELEV 56 FULL NOTAM SERVICE NOT AVBL

ŝ

UTC +8 VAR 2 DEG W

UNCR

323037S 1155000E AD OPR Royal Aero Club of WA. 41 Eagle Drive, Jandakot Airport, WA. 6164. Email: info@rovalaeroclubwa.com.au. PH 08 9417 0000. ARO 08 9581 6222. Fax 08 9417 0040.

REMARKS 1.

Restricted OPS, PPR from AD OPR.

LDG fees applicable.

HANDLING SERVICES AND FACILITIES

2.

WA

AVGAS AVBL for RACWA OPS. Non RACWA OPS AVBL by appointment 24HR PN. Not AVBL MON

AERODROME OBSTACLES

Numerous high voltage powerlines surround the aerodrome to the N and E.

PHYSICAL CHARACTERISTICS

5700/700 (102PSI) Sealed, RWY LEN 1.159M, WID 18 05/23 38a **RWS 90** Slope 0.25% down to SW. 09/27 30c 5700/ Unrated, Gravel, RWY LEN 903M, Slope WID 15 **RWS 60** 0.22% down to W.

AERODROME AND APPROACH LIGHTING

RWY 05/23 AFRU+PAL 119.1 LIRL

ATS AND AERODROME COMMUNICATION FACILITIES

FIA PERTH CENTRE 135.25 Circuit Area

FLIGHT PROCEDURES

Right hand circuits RWY 05 and RWY 09.

CTAF - AFRU 119.1

NOISE ABATEMENT PROCEDURES

- Circuit training permitted only BTN 0700-2200 Local. 1.
- RWY 27 TKOF not available (Emergency only). 2.
- 3. HEL OPS not permitted west of RWY 05/23. HEL CCTS not permitted RWY 09/27.
- CCTS restricted to ACFT not exceeding 200 horsepower. 4.

ADDITIONAL INFORMATION

- Animal hazard exists. 1
- 2. CAUTION: Low level aerobatics are conducted within 1NM of AD.
- PJE occur HJ on airfield up to FL150. Pilots advised to monitor CTAF and PH CEN for DZ 3. status.

CHARTS RELATED TO THE AERODROME

WAC 3462.