

## COMMUNICATIONS FAILURE: PROCEDURE IN IMC IF ABLE CTC BN ATC ON TEL: (07) 3866-3694

• Squawk 7600, comply with vertical navigation requirements, but not below MSA.

Track via the latest STAR clearance to the nominated runway, then fly the most suitable
approach in accordance with EBSA EMERC Section 1.5

approach in accordance with ERSA EMERG Section 1.5.

Changes: PROC NR, RNP S RWY 01R (AR).

