CHARTERS TOWERS AVFAX CODE 4411

ELEV 955

QLD UTC +10 YCHT 200237S 1461620E VAR 7 DEG E CERT

AD OPR Charters Towers Regional Council, PO Box 189, Charters Towers, QLD, 4820. Email: facilities@charterstowers.ald.gov.au. ARO 0428 440 143.

190° 1.9NM Charters Towers

REMARKS

AD Charges: \$10.00 inc. GST/tonne/landing.

HANDLING SERVICES AND FACILITIES

Fuel supplied by IOR Aviation Pty Ltd. JET A1 and AVGAS 100LL AVBL H24 self-serve bowser. Payment method via IOR Aviation tag for account holders or via the Fuelcharge APP.

PH 1300 457 467. Drums and drum filling AVBL H24 DLY - call out fees apply. Contact Ben Beatie 0490 114 711.

PASSENGER FACILITIES

PT/TX/HC/AC/LG/RF/WC/ME.

AERODROME OBSTACLES

- Group of TWR on hill is APRX 1,484FT AMSL BTN BRG 194.4 and 196.1 DEG MAG 3NM FM ARP and infringes conical SFC up to 393FT.
- 2. Lit TWR 1,190FT AMSL APRX 4,070M SOT 51M right of RWY CL infringes TKOF SFC by
- IWI located 95M SE of RWY 24 THR infringes TNS by 9FT.

PHYSICAL CHARACTERISTICS

01/19 008 33c PCN 6 /F /A /350 (51 PSI) /U THR bitumen seal, WID 23 RWS 60

remainder gravel.

AERODROME AND APPROACH LIGHTING

RWY 06/24 LIRL AFRU+PAL 126.7 SDBY PWR AVBL

RWY edge light spacing: 06/24: 60M.

OTHER LIGHTING

- Secondary PWR switchover time: 15 SEC.
- TWY LGT: Blue edge.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA BRISBANE CENTRE 120.55 Circuit area

LOCAL TRAFFIC REGULATIONS

- Due to the grades on RWY 06/24, the opposite ends of the RWY are not visible when TKOF. Mandatory CTAF BCST RQ before OPR on RWY.
- 2. From the TWY holding point, ACFT at THR RWY 24 may not be visible.

CTAF - AFRU 126.7

ADDITIONAL INFORMATION

- 1. Bird and animal hazard exists.
- Gliding OPS HJ JF Winch launched to 3,000FT. Glider OPS conducted from RWS, N side of RWY 06/24.
- 3. Model ACFT OPR within the AD locality.

CHARTS RELATED TO THE AERODROME

- 1. WAC 3234.
- 2. Also refer to AIP Departure and Approach Procedures.