
GARDEN ISLAND HELIPORT

ELEV 36



WA UTC +8 YGAD 321430S 1154102E VAR 2 DEG W MIL AD OPR NAVY, HMAS Stirling, Rockingham, WA, 6958. Email: stir.hsf@defence.gov.au. PH Airfield Manager: 08 9553 3921: 0448 719 837

REMARKS

- ACFT OPR in vicinity of HMAS Stirling (including embarked ACFT) CTC Airfield Manager 24HR PN.
- 2. MIL OPS only. HLS not open for public use.
- 3. REQ for use of FAC to be included in LOGREQ signalled to HMAS Stirling, attention: HSF Manager and PSM West. Port Manager (08 9553 2386) is responsible for coordinating all LOGREQ replies. REQ to disembark to, or use of FAC by detachments or flights, are to be signalled to HMAS Stirling, attention HSF Manager with PSM West as INFO addressee. The HSF Manager is responsible for coordinating use of the FAC.

HANDLING SERVICES AND FACILITIES

F44 24HR PN.

RESCUE AND FIREFIGHTING SERVICES

- 1. CAT 4 AVBL MON-FRI 2330 0800 UTC EXC PH. HO 24HR PN.
- ARFFS MNT CTAF 121.0 MHz.

AERODROME OBSTACLES

Numerous vegetation infringements of APCH, TKOF and transitional SFC in proximity of RWY 05/23.

METEOROLOGICAL INFORMATION PROVIDED

- METAR/SPECI.
- 2. AWIS Phone 08 6216 2614 Report faults to BoM.

PHYSICAL CHARACTERISTICS

05/23 048 15a PCN 12 /F /B /1000 (145PSI) /T WID 34 Slope 1.9% up to SW FM THR RWY 23 for 100M then 1.6% down to SW to THR RWY 05.

AERODROME AND APPROACH LIGHTING

RWY 05/23 LIRL PAL 124.1

RWY edge LGT non-standard spacing: less than 55M.

OTHER LIGHTING

- TWY edge LGT and APN edge LGT non-standard colour: yellow.
- 2. APN edge LGT non-standard spacing: greater than 30M.
- Holding point unlit.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA PERTH CENTRE 135.25 Circuit Area

LOCAL TRAFFIC REGULATIONS

All takeoffs and landings are to be made from the RWY sealed SFC due to limited movement area.

FLIGHT PROCEDURES

- ARR ACFT CTC "STIRLING TOWER" 156.7. 10 MIN PN advising intentions.
- Circuit HGT 500FT AGL. Circuit ALT BTN 200 2,000FT permitted. Non-standard circuit HGT to be advised.
- 3. Circuit direction: RWY 05 Right hand, RWY 23 Left hand.

CTAF 121.0

NOISE ABATEMENT PROCEDURES

- ACFT to remain 0.5NM clear of mainland when BLW 1,500FT AMSL, particularly Rockingham and Point Peron.
- 2. ACFT not to overfly HMAS Stirling FAC.

ADDITIONAL INFORMATION

- 1. HSF CS "STIRLING SUPPORT" 132.5 MHz MNT.
- 2. Flight deck procedure trainer (CS "TRAINER"), 393.5 MHz.
- 3. Flight deck procedure trainer lighting based on fast frigate guided lighting fit.

CHARTS RELATED TO THE AERODROME

WAC 3462.