


**MURRAY FIELD****ELEV 56****AVFAX CODE 6010****FULL NOTAM SERVICE NOT AVBL**

WA 323037S 1155000E UTC +8 YMUL  
 VAR 2 DEG W UNCR  
 AD OPR Royal Aero Club of WA, 41 Eagle Drive, Jandakot Airport, WA,  
 6164. Email: info@royalaeroclubwa.com.au. PH 08 9417 0000. ARO 08  
 9581 6222. Fax 08 9417 0040.

**REMARKS**

1. Restricted OPS. PPR from AD OPR.
2. LDG fees applicable.

**HANDLING SERVICES AND FACILITIES**

AVGAS AVBL for RACWA OPS. Non RACWA OPS AVBL by appointment 24HR PN. Not AVBL MON.

**AERODROME OBSTACLES**

Numerous high voltage powerlines surround the aerodrome to the N and E.

**PHYSICAL CHARACTERISTICS**

05/23	38a	5700/700 (102PSI) Sealed. RWY LEN 1,159M. WID 18	RWS 90
		Slope 0.25% down to SW.	
09/27	30c	5700/ Unrated. Gravel. RWY LEN 903M. Slope WID 15	RWS 60
		0.22% down to W.	

**AERODROME AND APPROACH LIGHTING**

RWY 05/23 LIRL AFRU+PAL 119.1

**ATS AND AERODROME COMMUNICATION FACILITIES**

FIA PERTH CENTRE 135.25 Circuit Area

**FLIGHT PROCEDURES**

Right hand circuits RWY 05 and RWY 09.

**CTAF - AFRU 119.1****NOISE ABATEMENT PROCEDURES**

1. Circuit training permitted only BTN 0700-2200 Local.
2. RWY 27 - TKOF not available (Emergency only).
3. HEL OPS not permitted west of RWY 05/23. HEL CCTS not permitted RWY 09/27.
4. CCTS restricted to ACFT not exceeding 200 horsepower.

**ADDITIONAL INFORMATION**

1. Animal hazard exists.
2. CAUTION: Low level aerobatics are conducted within 1NM of AD.
3. PJE occur HJ on airfield up to FL150. Pilots advised to monitor CTAF and PH CEN for DZ status.

**CHARTS RELATED TO THE AERODROME**

WAC 3462.