


**WILLIAMSON****ELEV 104****AVFAX CODE 4419****FULL NOTAM SERVICE NOT AVBL**

QLD 222824S 1501042E UTC +10 YWIS  
 VAR 9 DEG E UNCR  
 AD OPR DCSO Rockhampton, 68 Western Street, Rockhampton, QLD,  
 4700. PH 07 4935 5000. Fax 07 4935 5024.

**REMARKS**

1. PPR.
2. Contact range control on 07 4935 5000 prior to DEP to CFM  
FREQ RQMNTS.
3. Caution: This aerodrome is not subject to routine serviceability inspection or NOTAM advice of unserviceabilities. Additional aerodrome data is available from the contact telephone numbers above or for Mil Aircrew: <http://drnet.defence.gov.au/ARMY/FORCOMD/Headquarters/AviationBranch/AvnAwDir/Pages/OPAW.aspx>

**AERODROME OBSTACLES**

High terrain 2.2NM N of AD.

**METEOROLOGICAL INFORMATION PROVIDES**

1. METAR/SPECI.
2. AWIS PH 07 3564 3747 - Report faults to BoM.

**ATS AND AERODROME COMMUNICATION FACILITIES**

FIA BRISBANE CENTRE 119.55 4000FT

**LOCAL TRAFFIC REGULATIONS**

1. Apron PRKG AVBL E of middle of RWY 14/32. PRKG area unsealed and ill defined. Access in wet weather may be RESTR due to flooding of TWYs.
2. MAX RAD 180DEG turns MUST be taken at turning nodes with back-and-fill turns (3 point turns) being taken across WID of RWY.
3. Apron access requires movement over concrete culverts with grades of more than 2 degrees. Apron access is not AVBL for C17 ACFT.
4. Restriction: C-17 ACFT not permitted to conduct 180DEG turns on RWY, ACFT shall conduct STAR turns at turning nodes only.

**CTAF** 126.7**ADDITIONAL INFORMATION**

Kangaroo hazard exists, particularly around dawn and dusk.

**CHARTS RELATED TO THE AERODROME**

1. WAC 3235.
2. MIL Aerodrome Obstruction Chart Type A: NOV 2019.