

AIP SUPPLEMENT (SUP)

AERONAUTICAL INFORMATION SERVICE,
AIRSERVICES AUSTRALIA, GPO BOX 367,
CANBERRA ACT 2601

AIRAC

H195/25

Effective: 202511262300 UTC

For **DISTRIBUTION** queries, contact:
Email: aim_editorial@airservicesaustralia.com

For **CONTENT** queries regarding this SUP, contact:
Email: docs.amend@airservicesaustralia.com

AMENDMENTS TO AIP DESIGNATED AIRSPACE HANDBOOK (DAH) AND EN ROUTE SUPPLEMENT AUSTRALIA (ERSA) EFFECTIVE 27 NOVEMBER 2025

1. INTRODUCTION

- 1.1 This SUP will cancel and replace SUP H132/25 and SUP H170/25 with a change to the cancellation date.
- 1.2 The purpose of this SUP is to amend Section 22 (IFR WAYPOINTS) of the DAH and IFR Waypoints of the ERSa effective 27 November 2025.

2. ACTION

2.1 Add the following new waypoints to DAH Section 22:

DUDUT	340453.3S	1414109.8E	FD2ZH	401004.4S	1475627.1E
FD2WA	401525.0S	1474908.0E	FD2ZI	401010.5S	1474622.0E
FD2WB	401251.9S	1474225.5E	FD2ZM	400610.3S	1475818.8E
FD2WC	400709.7S	1474315.7E	FS2EA	222031.5S	1194009.5E
FD2WF	400804.4S	1475352.5E	FS2EB	222616.8S	1194014.9E
FD2WH	400957.3S	1475822.7E	FS2EC	222819.5S	1193427.6E
FD2WI	401028.2S	1474809.2E	FS2EF	222038.6S	1193119.2E
FD2ZA	401510.2S	1474646.3E	FS2EH	221608.2S	1192410.9E
FD2ZB	401210.3S	1474023.1E	FS2EI	222327.7S	1193547.0E
FD2ZC	400632.8S	1474152.6E	FS2WD	221425.9S	1191227.8E
FD2ZF	400810.7S	1475220.6E	FS2WE	220840.6S	1191222.3E

FS2WF	221418.6S	1192117.4E	MI2EF	341450.7S	1421149.6E
FS2WG	220637.6S	1191808.7E	MI2EH	341314.0S	1420222.5E
FS2WH	221849.1S	1192825.6E	MI2EI	341551.1S	1421744.1E
FS2WI	221129.5S	1191649.8E	MI2SD	342632.0S	1420941.8E
IBIMO	340520.9S	1420134.6E	MI2SE	342924.2S	1420341.0E
LAPAM	313439.1S	1160008.8E	MI2SF	341925.3S	1420445.2E
LT2ND	412455.3S	1465834.3E	MI2SG	342542.0S	1415822.6E
LT2NE	411936.4S	1470127.0E	MI2SH	341126.3S	1420536.3E
LT2NF	412800.9S	1470839.1E	MI2SI	342424.7S	1420413.1E
LT2NG	411808.4S	1471042.1E	MI2WF	341231.1S	1415812.5E
LT2NI	412348.2S	1470503.9E	MI2WH	341408.1S	1420739.4E
LT2SA	414202.1S	1472937.4E	MI2WI	341130.1S	1415218.3E
LT2SB	414734.5S	1472526.2E	MI2WJ	341545.9S	1414908.5E
LT2SC	414721.4S	1471746.4E	MI2WK	341028.8S	1414624.3E
LT2SF	413910.1S	1471811.8E	MI2WL	340632.8S	1415125.7E
LT2SH	413036.0S	1471051.5E	MX400	220603.4S	1480500.0E
LT2SI	414322.3S	1472148.8E	MX410	220105.8S	1480411.6E
LV2EA	282804.4S	1223712.0E	MX420	215923.9S	1480501.4E
LV2EB	283120.3S	1224233.6E	MX430	215925.8S	1480722.7E
LV2EC	283654.3S	1224055.2E	MX440	220053.3S	1480941.9E
LV2EF	283449.9S	1223154.9E	MX450	220217.5S	1481155.8E
LV2EH	283737.0S	1222323.5E	NZ2SA	303224.8S	1495135.5E
LV2EI	283305.3S	1223714.3E	NZ2SB	303433.4S	1494525.5E
LV2WD	284529.5S	1221438.0E	NZ2SC	303016.5S	1494059.8E
LV2WE	284213.0S	1220916.3E	NZ2SF	302447.8S	1494803.5E
LV2WF	283844.5S	1221956.1E	NZ2SH	301659.2S	1495009.5E
LV2WG	283639.3S	1221055.8E	NZ2SI	302940.6S	1494644.6E
LV2WH	283536.8S	1222931.6E	PD2ND	201646.6S	1182459.7E
LV2WI	284028.8S	1221436.3E	PD2NE	201109.3S	1182618.6E
MI2EA	341135.2S	1422053.7E	PD2NF	201832.9S	1183330.2E
MI2EB	341651.5S	1422338.7E	PD2NG	201023.8S	1183221.3E
MI2EC	342048.4S	1421836.9E	PD2NH	202427.8S	1183915.7E

PD2NI	201451.1S	1182954.4E	SE2WH	412050.6S	1482200.0E
PD2SA	202906.3S	1185035.2E	SE2WI	411827.1S	1480100.1E
PD2SB	203443.7S	1184916.4E	SE2WM	412014.9S	1481644.9E
PD2SC	203529.2S	1184312.8E	SK2SA	112919.1S	1305141.3E
PD2SF	202720.3S	1184203.9E	SK2SB	113503.8S	1305114.4E
PD2SH	202125.5S	1183618.1E	SK2SC	113636.6S	1304536.6E
PD2SI	203102.0S	1184540.1E	SK2SF	112841.0S	1304322.3E
RMX01	220050.4S	1480600.1E	SK2SH	112334.6S	1303704.9E
RMX02	220105.7S	1480610.5E	SK2SI	113152.4S	1304718.3E
SALEB	312929.7S	1155927.7E	SK2SM	112529.6S	1303926.4E
SE2EA	412654.1S	1483249.0E	TV2ED	375721.5S	1463553.6E
SE2EB	412247.8S	1483809.9E	TV2EE	375846.2S	1464553.4E
SE2EC	411737.7S	1483453.1E	TV2EF	380757.4S	1463413.8E
SE2EF	412109.6S	1482503.7E	TV2EG	380641.3S	1464738.7E
SE2EH	411623.2S	1482306.0E	TV2EH	381418.8S	1462608.5E
SE2EI	412158.9S	1483136.7E	TV2EI	380343.0S	1463936.9E
SE2EM	412019.9S	1481830.9E	TV2WA	382501.1S	1462017.2E
SE2WD	412250.6S	1475749.5E	TV2WB	382342.6S	1461408.8E
SE2WE	411742.1S	1475426.5E	TV2WC	381803.1S	1461254.3E
SE2WF	411912.0S	1480733.7E	TV2WF	381639.1S	1462309.6E
SE2WG	411332.8S	1475941.3E	TV2WH	381100.2S	1463021.5E
			TV2WI	382010.8S	1461839.3E

2.2 Add the following new waypoints to DAH Section 22 and ERSa IFR WAYPOINTS.

AGSUL	345254.6S	1504948.4E	UBMEP	344613.2S	1504453.5E
-------	-----------	------------	-------	-----------	------------

2.3 Delete the following waypoints from DAH Section 22:

ET2EI	FLIZA	LTVEE	MIASG	NBRSA	SNBSC
ET2WI	FLIZB	LTVEF	MIASH	NBRSB	SNBSF
FDFEA	FLIZC	LTVEG	MIASI	NBRSC	SNBSH
FDFEB	FLIZF	LTVEH	MIAWF	NBRSF	SNBSI
FDFEC	FLIZH	LTVEI	MIAWH	NBRSH	SNBSM
FDFEF	FLIZI	LTVWA	MIAWI	NBRSI	STHEA
FDFEH	FLIZM	LTVWB	MIAWJ	PPDND	STHEB
FDFEI	LTNEA	LTVWC	MIAWK	PPDNE	STHEC
FDFWD	LTNEB	LTVWF	MIAWL	PPDNF	STHEF
FDFWE	LTNEC	LTVWH	MLTND	PPDNG	STHEH
FDFWF	LTNEF	LTVWI	MLTNE	PPDNH	STHEI
FDFWG	LTNEH	MIAEA	MLTNF	PPDNI	STHEM
FDFWH	LTNEI	MIAEB	MLTNG	PPDSA	STHWD
FDFWI	LTNWD	MIAEC	MLTNI	PPDSB	STHWE
FLIWA	LTNWE	MIAEF	MLTSA	PPDSC	STHWF
FLIWB	LTNWF	MIAEH	MLTSB	PPDSF	STHWG
FLIWC	LTNWG	MIAEI	MLTSC	PPDSH	STHWH
FLIWF	LTNWH	MIASD	MLTSF	PPDSI	STHWI
FLIWH	LTNWI	MIASE	MLTSH	SNBSA	STHWM
FLIWI	LTVED	MIASF	MLTSI	SNBSB	

2.4 Delete the following waypoints from the DAH Section 22 and ERSA IFR WPT:

ENDIS	POTAD
-------	-------

3. CANCELLATION

3.1 This SUP will be cancelled when it is incorporated into AIP DAH and ERSA expected 09 July 2026.

4. DISTRIBUTION

4.1 Airservices Australia website only.