ELEV 869

			FULL NOTAM	SERVICE	NOT AVBL
41	QLD		UTC +10		YESD
110° 1.0NM	252154S	1510630E		-	UNCR
∖∖ Eidsvold			nal Council, PO Box 390		
	Email: admin@northburnett.qld.gov.au. Council PH 1300 696 272. Fax 07				
_ ≯	4161 1425.				
	REMARKS				
	1. No parking on or near areas allocated for EMERG parking.				
L.	2. Suitable for ACFT up to 5,700KG MTOW.				
34	0	PR.			
PASSENGER FACILITIES					
LG/WC.					
AERODROME OBSTACLES					
 Transition and fly-over OLS infringement exists on both sides of RWS due to trees. 					
2. Primary wind indicator infringes the transitional OLS.					
3. COM TWY LOC E of RWY infringes the transitional OLS by 21M.					
PHYSICAL CHARACTERISTICS					
14/32		nrated. Gravel and g ope 0.3% down to N	grass. RWY LEN 1,189M IW.	. WID 30	RWS 45
AERODROME AND APPROACH LIGHTING					
RWY 14/32 LIR	L(1)	AFRU+PAL 126.7		SDBY PW	/R AVBL
(1) EMERG OP	S only				
ATS AND AERODROME COMMUNICATION FACILITIES					
FIA BRISBA	NE CENTR	RE	124.1		
CTAF - AFRU 126.7					
ADDITIONAL INFORMATION					
Fly airstrip for wildlife prior to landing.					
WAC 3340.					
WAC 3340.					