
15 JUN 2023



TONEG FOUR DEPARTURE

RWY 06L (RNAV) MAX IAS 150KT until established to intercept TRK to TONEG

- Track 056°
- AT or ABV 600ft turn LEFT to intercept and track 240° to TONEG
- Continue tracking 240° thence as cleared.

RWY 24R (RNAV)

- Track 236°
- . AT or ABV 600ft, intercept and track 240° to TONEG
- Continue tracking 240° thence as cleared.

RWY 12 (RNAV) MAX IAS 150KT until established to intercept TRK to TONEG

- Track 116°
- AT or ABV 600ft turn RIGHT track 282°
- Intercept and track 240° to TONEG
- Continue tracking 240° thence as cleared.

RWY 30 (RNAV) MAX IAS 150KT until established to intercept TRK to TONEG

Track 296°

- ATor ABV 600ft, turn LEFT track 168°
- Intercept and track 240° to TONEG
- Continue tracking 240° thence as cleared.

COMMUNICATIONS FAILURE PROCEDURE

On recognition of communications failure

- Squawk 7600
- · Maintain procedure track for two minutes, and
- CLIMB IF NECESSARY TO MINIMUM SAFE ALTITUDE, to maintain terrain clearance, then
- Proceed in accordance with the latest ATC route clearance acknowledged.

Changes: Editorial. PJTDP03-175

