### FAC YCRE - 1

L

## 

CRESSY		ELEV 420		
	FULL NOTAM SERVIC	CE NOT AVBL		
VIC	UTC +10	YCRE		
380224S 143391	1E VAR 11 DEG E	UNCR		
AD OPR CSS Investments, 175 Aerodrome Road, Cressy, VIC, 3320. Email:				
cressyaerodrome@iinet.net.au. PH 0481 327 587.				
	sit of			
288° 1.1NM Cressy				
Ciessy				
	33			
07				

### REMARKS

PPR.

# HANDLING SERVICES AND FACILITIES

No fuel AVBL.

PASSENGER FACILITIES

WC/RF/HC/AC.

### AERODROME OBSTACLES

1. Powerlines on the approach to RWY 33.

Unlit TWY 355 DEG MAG 0.8NM FM ARP. 2.

### PHYSICAL CHARACTERISTICS

01/19	36c	Grass. RWY LEN 1100M
15/33	30c	Grass, RWY LEN 900M

### AERODROME AND APPROACH LIGHTING

RWY 01/19 PTBL(1) BY PRIOR

**WID 50** 

**WID 50** 

#### (1) 30MIN PN.

### ATS AND AERODROME COMMUNICATION FACILITIES 126.8

FIA MELBOURNE CENTRE

### FLIGHT PROCEDURES

- 1. Right hand circuits when operating on RWY 01 and 33.
- Pilots are encouraged to avoid overflying Cressy township and properties to the S. 2.
- Aircraft approaching from NW or W to track via Lake Rosine and when approaching from S 3. track via the eastern shore of Lake Weering.

### **CTAF** 126.7

### ADDITIONAL INFORMATION

Railway tracks are close to the threshold of RWY 15 and 19.

### CHARTS RELATED TO THE AERODROME

WAC 3469.

ARRANGEMENT