

**MURRIN MURRIN****ELEV 1535****AVFAX CODE 6107**

WA  
284219S 1215326E UTC +8 YMMI  
VAR 1 DEG E CERT  
AD OPR Minara Resources Pty Ltd, Murrin Murrin Operations, PO Box  
Z5523, Perth, WA, 6831. Email: siteservices.supt.coord@glencore.com.au.  
PH 08 9088 5957 (BH). ARO 0408 941 791. Mobile 0408 657 461 (AH).

**REMARKS**

Restricted Operations. PPR from AD Manager/AROs.

**HANDLING SERVICES AND FACILITIES**

Nil fuel AVBL.

**PASSENGER FACILITIES**

LG/WC/PT

**AERODROME OBSTACLES**

1. Illuminated WDI 209M N of RWY 03 start of TORA 100M E of RWY CL infringes transitional SFC by 10FT.
2. Transient E190 ACFT tail 1,567FT AMSL BRG 209 DEG MAG 885M FM ARP. Infringes TNS by 11FT.

**PHYSICAL CHARACTERISTICS**

03/21 034 66a PCN 22 / F / A / 1100 (160PSI) / T Sealed. WID 30 RWS 150

**AERODROME AND APPROACH LIGHTING**

RWY 03/21 LIRL SDBY PWR AVBL  
RWY 03/21 PAPI(1) 3.0 DEG50FT SDBY PWR AVBL

(1) Left side.

1. RWY edge light spacing: 03/21: nominal 90M.
2. Lighting manually activated. 30MIN PN.

**OTHER LIGHTING**

1. Standby PWR derived from generator. Switchover time: 10 SEC.
2. TWY LGT: Blue edge.

**ATS AND AERODROME COMMUNICATION FACILITIES**

FIA MELBOURNE CENTRE 118.4 Circuit Area

**LOCAL TRAFFIC REGULATIONS**

1. ACFT ABV 5,7000KG to use MAX RAD MNM speed turns at RWY ends only.
2. Second ACFT PRKG AVBL on RWY adjacent to TWY entrance. NOTAM will be issued advising RWY not AVBL. CTC ARO.

**CTAF - AFRU 126.8**

AFRU signal not AVBL on ground Laverton, Murrin Murrin or Sunrise Dam. AFRU located at Leonora.

**ADDITIONAL INFORMATION**

Mine site 2.5NM, BRG 179DEG M.

**CHARTS RELATED TO THE AERODROME**

1. WAC 3352.
2. Also refer to AIP Departure and Approach Procedures.