

**SOUTHPORT****ELEV 5****AVFAX CODE 4016****FULL NOTAM SERVICE NOT AVBL**

QLD 275518S 1532217E UTC +10 YSPT  
 VAR 11 DEG E UNCR  
 AD OPR Southport Flying Club, PO Box 184, Runaway Bay, QLD, 4216. PH 07  
 5594 7394. ARO 0412 412 632: 0418 722 318.

150° 3.5NM  
Southport**REMARKS**

1. Restricted OPS: PPR FM AD OPR.
2. No public or commercial OPS permitted.
3. Multi ENG OPS not permitted.

**AERODROME OBSTACLES**

Transition surfaces infringed by trees.

**PHYSICAL CHARACTERISTICS**

01/19 26c Unrated. Natural. Central 15M sealed. RWY WID 18 RWS 60  
 LEN 778M.

1. RWY 01 DTHR 190M.
2. RWY 19 DTHR 140M.

**AERODROME AND APPROACH LIGHTING**

RWY 01/19 LIRL(3)

BY PRIOR  
ARRANGEMENT

RWY 01 PAPI(1) 5.0 DEG50FT

RWY 19 PAPI(2) 5.0 DEG50FT

- (1) Right side.
- (2) Left side.
- (3) Contact ARO.

**ATS AND AERODROME COMMUNICATION FACILITIES**

FIA BRISBANE CENTRE 119.5 On Ground

**FLIGHT PROCEDURES**

1. Right hand CCTS RQ when OPR on RWY 19.
2. COASTAL TRANSIT IN CLASS G AIRSPACE  
 Due high density TFC low level coastal ACFT should fly:  
 Southbound - 1,000FT AMSL  
 Northbound - 500FT AMSL  
**CAUTION: Concentrated TFC BTN Southport and Gold Coast at 500FT - see also GOLD COAST CTAF procedures.**
3. No straight in approaches on either RWY.

**CTAF - AFRU 119.0****NOISE ABATEMENT PROCEDURES**

Noise abatement applies - contact AD OPR.

**ADDITIONAL INFORMATION**

Bird and animal hazard exists.

**CHARTS RELATED TO THE AERODROME**

WAC 3340, 3357.