

**AERONAUTICAL
INFORMATION
CIRCULAR (AIC)****H29/24****Effective: 202407291930 UTC**

AERONAUTICAL INFORMATION SERVICE,
AIRSERVICES AUSTRALIA, GPO BOX 367,
CANBERRA ACT 2601

For **DISTRIBUTION** queries, contact:
Email: aim_editorial@airservicesaustralia.com

For **CONTENT** queries regarding this AIC, contact:
Email: rmackay@gcal.com.au

GOLD COAST AIRPORT (YBCG) RUNWAY 17/35 CLOSURE DUE TO DRAIN VEGETATION REMOVAL

1. INTRODUCTION

1.1 This AIC intends to provide information and notification regarding an upcoming runway closure at Gold Coast Airport (YBCG) necessary to facilitate airside drain vegetation removal activities.

Runway 17/35 which is the smaller, crosswind secondary runway at YBCG is currently scheduled for closure for four days:

- 202407291930 until 202408020800 UTC

1.2 Notification of this closure this will also be promulgated via NOTAM.

2. TECHNICAL INFORMATION

2.1 Whilst the scheduled vegetation removal activity is underway Runway 17/35 will be closed to aircraft during the time period denoted above.

3. CONTACT DETAILS

- 3.1 Further information or clarification pertaining to this advice may be obtained by contacting Gold Coast Airport Pty Ltd:

Riley Mackay

Airside Operations Supervisor

Gold Coast Airport

Phone: +61 7 5589 1127

Mobile: +61 (0) 431 661 640

Email: rmackay@gcal.com.au

4. CANCELLATION

- 4.1 This AIC will self-cancel at 202408020800 UTC.

5. DISTRIBUTION

- 5.1 Airservices Australia website only.