


**BARWON FIELD****ELEV 260****FULL NOTAM SERVICE NOT AVBL**

VIC  
 380849S                      1441021E                      UTC +10                      YGBF  
 AD OPR Craig Taberner, 470 Pollocksford Rd, Gnarwarre, VIC, 3221. Email:  
 ctaberne@ford.com. PH 0439 154 202 (H24).                      VAR 11 DEG E                      UNCR

**REMARKS**

PPR.

**PHYSICAL CHARACTERISTICS**

02/20	28c	Grass. RWY LEN 850M	WID 15
15/33	28c	Grass. RWY LEN 850M	WID 15

**ATS AND AERODROME COMMUNICATION FACILITIES**

FIA	MELBOURNE CENTRE	134.325
-----	------------------	---------

**FLIGHT PROCEDURES**

1. Right hand circuits for RWY 02 and RWY 33.
2. No landing on RWY 02 due to rising terrain to south.

**CTAF** 119.0**ADDITIONAL INFORMATION**

Pilots should consider noise impacts and avoid overflying residential buildings.

**CHARTS RELATED TO THE AERODROME**

WAC 3469, 3470.