
# KENS BORE AVFAX CODE 6806

ELEV	709
------	-----

YKBA

CFRT

WA UTC +8 220925S 1160926E VAR 1 DEG E AD OPR Onslow Iron Pty Ltd, 20 Walters Drive, Osborne Park, WA, 6017. Email: kensbore.airport@mrl.com.au. PH H24 Airport Supervisor 0498 513 268. Website: www.mineralresources.com.au.



## REMARKS

- 1. Restricted OPS. PPR FM Airport Supervisor.
- 2. Parking allocation by prior arrangement with Airport Supervisor.

### HANDLING SERVICES AND FACILITIES

Marshalling and ground handling services by prior arrangement with Airport Supervisor.

#### **PASSENGER FACILITIES**

WC and Telstra 4G reception.

#### **APRONS AND TAXIWAYS**

TWY A: Code C, 23M sealed.

#### **AERODROME OBSTACLES**

RWY 14 secondary IWI BRG 325 DEG MAG 652M FM ARP. Infringes TNS by 0.41FT.

#### PHYSICAL CHARACTERISTICS

14/32 134 69a PCN 44 /F /A /1448 (210PSI) /T Grooved. WID 30 RWS 280

## **AERODROME AND APPROACH LIGHTING**

RWY 14/32	LIRL	PAL+AA 120.15	
RWY 14/32	PAPI(1)	PAL+AA 120.15	3.0 DEG53.3FT
(4) 1 6	• •		

# Left side.

## OTHER LIGHTING

TWY LGT: blue edge.

## ATS AND AERODROME COMMUNICATION FACILITIES

FIA	MELBOURNE CENTRE	122.4		
FIA	MELBOURNE CENTRE	125.7		
UNICOM	KENS BORE UNICOM	126.7 (1)		
(1) CS "Kens Bore UNICOM"				

(1) CS "Kens Bore UNICOM".

## LOCAL TRAFFIC REGULATIONS

- 1. All fixed wing ACFT ABV 20,000KG must make MAX RAD turns at MNM speed at all turning pads to avoid SFC damage.
- 2. All ACFT to follow APN markings.
- All jet ACFT to use idle power for movements on the APN with the exception of breakaway thrust to initiate taxi. ACFT that cannot comply with this restriction must advise the AD OPR prior to departure.
- 4. RWS not AVBL from flight OPS.

#### CTAF - AFRU 126.7

AFRU located at YBGD. Not AVBL on ground.

# CHARTS RELATED TO THE AERODROME

- 1. WAC 3229.
- 2. Also refer to AIP Departure and Approach Procedures.