FLEV 385

BALLERA AVFAX CODE 4135

د/

OI D UTC +10 YILF 272430S 1414830F VAR 8 DEG E CFRT AD OPR Santos Ltd. PO Box 2319. Adelaide. SA. 5001. PH 08 8116 5213. ARO 07 4646 8103.

REMARKS

- Restricted OPS. PPR for all OPS. 1.
- 2 All OPS: advise AD OPR at least 20MIN prior to ETA on 126.4. CS 'Ballera Base'. 3
 - AD Charges: Non-company aircraft.
 - Bay 2 for all jet refuelling.

4 HANDLING SERVICES AND FACILITIES

Private terminal facilities. JET A1 private facility.

METEOROLOGICAL INFORMATION PROVIDED

- 1 TAF CAT C, METAR/SPECI.
- 2. AWIS PH 07 3564 3702 - Report faults to BoM.
- AWIS FREQ 128.65 Report faults to Santos Limited. 3.

PHYSICAL CHARACTERISTICS

032 59a PCN 30 /F /A /1130 (164PSI) /T Sealed 03/21 WID 30 **RWS 150**

AERODROME AND APPROACH LIGHTING

RWY 03/21	LIRL	PAL+AA 120.05	
RWY 03/21	PAPI(1)	PAL+AA 120.05	3.0 DEG48FT
RWY 03/21	PTBL(2)		

(1)Left side.

- (2)EMERG only. 60MIN PN.
- Secondary PWR MAN activated 45 MIN PN. 1.
- 2. RWY 03/21 edge light spacing: 60M.

OTHER LIGHTING

TWY LGT: Blue edge.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA BRISBANE CENTRE 118.8 Circuit area

LOCAL TRAFFIC REGULATIONS

- ACFT ABV 5.700KG must use RWY turning nodes for 180 DEG turns. 1.
- 2. Requirement for all ACFT to taxi to turning nodes and execute MAX radius turns. November to March inclusive.

FLIGHT PROCEDURES

- No circling to the W of AD. 1.
- 2. Right hand circuits RWY 03.

CTAF - AFRU 126.7

ADDITIONAL INFORMATION

- CAUTION: High pressure gas discharge 1.600M N of AD (D611). 1.
- 2. Increased wildlife activity will be communicated via NOTAM as required. Pilots are encouraged as part of flight planning to REQ current information from AD safety personnel on 07 4646 8103.

CHARTS RELATED TO THE AERODROME

- WAC 3342. 1
- 2. Also refer to AIP Departure and Approach Procedures.

SDBY PWR AVBL SDBY PWR AVBL BY PRIOR ARRANGEMENT