


**MELTON****ELEV 670****FULL NOTAM SERVICE NOT AVBL**

VIC  
373718S 1443356E UTC +10 YMEL  
VAR 11 DEG E UNCR  
AD OPR E. Reeve, 995 Coburns Road, Toolern Vale, VIC, 3337. Email:  
info@meltonairservices.com.au. PH 03 9746 1342. Website:  
www.meltonairservices.com.au.

**REMARKS**

PPR - Contact Melton Air Services, PH AD OPR.

**HANDLING SERVICES AND FACILITIES**

AVGAS AVBL, CTC AD OPR. Cash, V and MC accepted.

**PASSENGER FACILITIES**

LG/WC/RF/TX/ME.

**PHYSICAL CHARACTERISTICS**

04/22	44c	Unrated. Grass/Gravel. RWY LEN 1,340M.	WID 30	RWS 60
		RWY 22 DTHR 90M. Slope 1% down to SW.		
10/28	33c	Unrated. Grass. RWY LEN 1,000M. RWY 28	WID 30	RWS 60
		DTHR 90M. Slope 1% down to SE.		
14/32	39c	Unrated. Grass. RWY LEN 1,200M. Slope 1%	WID 30	RWS 60
		up to N.		
16/34	21c	Unrated. Grass. RWY LEN 650M. Slope 1% up	WID 30	
		to N.		

**AERODROME AND APPROACH LIGHTING**

RWY 04/22 LIRL

BY PRIOR  
ARRANGEMENT

RWY 04/22 edge light spacing: 89M.

**ATS AND AERODROME COMMUNICATION FACILITIES**

FIA MELBOURNE CENTRE 135.7 Circuit Area

**LOCAL TRAFFIC REGULATIONS**

All ACFT DEP (other than touch and go OPS) to commence take off roll from RWY end to maximise height over residential areas after take off.

**FLIGHT PROCEDURES**

1. Where possible, ACFT should conform to established RWY direction.
2. Arrivals - at least 3 legs of the circuit to be flown.
3. Straight in approaches are not permitted.
4. RH Circuits RWY 04 and 10.
5. Landings only RWY 34.
6. Take off/landing RWY 16 not permitted.
7. All ACFT to avoid overflying Toolern Vale township NE of aerodrome.

**CTAF** 121.6**CHARTS RELATED TO THE AERODROME**

WAC 3469, 3470.