MANGROVE MOUNTAIN GLIDING

ELEV 1020 FULL NOTAM SERVICE NOT AVBL

NSW UTC +10 YMVM
331706S 1511246E VAR 12 DEG E UNCR
AD OPR Central Coast Soaring Club, 156 Bloodtree Rd, Mangrove Mountain,
NSW, 2250. PH 0402 907 038 (Club Phone) or 0414 256 602 (CFI). Website:
www.ccsoaring.com.au.

REMARKS
PPR for all ACFT (EXC powered EMERG service ACFT) - CTC AD OPR.

AERODROME OBSTACLES
Tall trees on approach to all RWY ends.

PHYSICAL CHARACTERISTICS

07/25 10c Unrated. Grass. Downslope to the W.

18/36 39c Unrated. Undulating grass.

RWY 18/36 very soft and unusable after rain.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA SYDNEY CENTRE 125.8

LOCAL TRAFFIC REGULATIONS

Practice glide approaches by powered ACFT are discouraged due to risk of conflict with winch operations and noise abatement.

FLIGHT PROCEDURES

- Avoid overfly below 3,500FT AMSL due to potential conflict with winch launching gliders.
- ACFT transiting the circuit area should BCST and MNT CTAF when in the vicinity of Mangrove Mountain.

CTAF 132.1

ADDITIONAL INFORMATION

- 1. Gliding OPS HJ launched by winch, cable up to 4,000FT in length.
- Intensive glider OPS including aerobatics within 10NM up to 8000FT AMSL.
- 3. Wind shear in moderate winds from any direction.
- Transiting aircraft should maintain a lookout when transiting the area due to the possibility
 of conflict with gliders in thermals anywhere in the vicinity.

CHARTS RELATED TO THE AERODROME

WAC 3456.