PROMINENT HILL AVEAX CODE 5206

FLFV 741

SA UTC +9:30 YPMH
294304S 1353128E VAR 6 DEG E CERT
AD OPR OZ Minerals, 2 Hamra Drive, Adelaide Airport, SA, 5950. Email:
airportcoordinators@bhp.com. PH Aviation Supervisor 0417 844 183. ARO H24
0427 594 817.

REMARKS
Restricted OPS: PPR FM AD OPR.

HANDLING SERVICES AND FACILITIES

VIVA Energy Aviation: JET A1 CTC ARO.

Marshalling, parking allocation and ground handling by prior arrangement with AD OPR.

PASSENGER FACILITIES

LG/RF/WC. Telstra 4G mobile reception.

PHYSICAL CHARACTERISTICS

18/36 184 72a PCN 26 /F /B /980 (142PSI) /T WID 30 RWS 150

AERODROME AND APPROACH LIGHTING

RWY 18/36 LIRL PAL+AA 122.8

RWY 18/36 PAPI(1) PAL+AA 122.8 3.0 DEG45FT

RWY 18/36 PTBL(2) BY PRIOR ARRANGEMENT

- (1) Left side.
- (2) 60MIN PN. CTC ARO.
- 1. RWY edge light spacing: 18/36: 60M.
- Selection of PAL HJ will activate PAPI only EXC where low LGT conditions exist due WX. Normal RWY LGT activation HN.
- APN LGT AVBL Bay 3 only.

OTHER LIGHTING

TWY LGT: Blue edge.

ATS AND AERODROME COMMUNICATION FACILITIES

FIA MELBOURNE CENTRE 122.0 7000FT

LOCAL TRAFFIC REGULATIONS

- RWY 18/36 ACFT ABV 5,700KG MTOW must make MAX radius turns at MNM speed at turn pads to avoid SFC damage.
- Refuelling AVBL Bay 3 only.

FLIGHT PROCEDURES

- Right hand CCTS RQ when OPR RWY 18.
- ACFT to avoid overflying the mine and plant areas E of AD due obstacles and blasting.

CTAF - AFRU 126.6

ADDITIONAL INFORMATION

Bird hazard exists. Nankeen Kestrel may be present in VCY of AD.

CHARTS RELATED TO THE AERODROME

- 1. WAC 3354.
- 2. Also refer to AIP Departure and Approach Procedures.