

**WINDARLING****ELEV 1502****AVFAX CODE 6119**

WA

UTC +8

YWDG


300155S

1192314E

VAR 0 DEG E

CERT

AD OPR Yilgarn Iron Pty Ltd, 20 Walters Dr, Osborne Park, WA, 6017. Email:  
windarling.aerodrome@mrl.com.au. ARO 0419 326 117, if not AVBL PH AD manager 0407 148  
536.

**REMARKS**

Restricted OPS: PPR.

**APRONS AND TAXIWAYS**

TWY A: sealed, WID 15M.

**AERODROME OBSTACLES**

Vegetation:

- 3FT AGL PSN 50M north of RWY CL for the entire length of RWY 10/28 infringes transitional SFC.
- 8FT AGL BTN BRG 271 - 110 DEG MAG, 0.50 - 0.51NM FM ARP.
- 8FT AGL BTN BRG 285 - 102 DEG MAG, 0.52 - 0.54NM FM ARP.

**PHYSICAL CHARACTERISTICS**

10/28 103 61a PCN 8 /F /A /522 (76PSI) /T Sealed WID 30 RWS 90

**AERODROME AND APPROACH LIGHTING**

RWY 10/28 PTBL(1)

BY PRIOR  
ARRANGEMENT

(1) EMERG only. 90MIN PN to ARO.

**ATS AND AERODROME COMMUNICATION FACILITIES**

FIA MELBOURNE CENTRE 123.4 Circuit area.

**LOCAL TRAFFIC REGULATIONS**

- From the TWY holding point, ACFT at THR RWY 28 may not be visible.
- ACFT at THR RWY 10 and 28 may not be visible to each other.
- ACFT ABV 5,700KG MTOW must turn at RWY ends only. MAX radius MNM speed turns.

**CTAF - AFRU** 126.7**CHARTS RELATED TO THE AERODROME**

- WAC 3351.
- Also refer to AIP Departure and Approach Procedures.